



kindex[®]

< Scan QR to view this original record online, or visit <https://jfk.kindex.org/s/431569>

Title: **104-10162-10242_p95.png**
Provenance: **National Archives**

Category: **Uncategorized**
Person:
Date:

SECRET

TO: Collyer/Beresford

TED Comments: Station requested VOACRS comments re failure STA-54.

FROM: S/BD

W/E Mr. Loftus (by phone X6067)

DATE: 28 Sept 1959

SECRET

BUENOS AIRES INFO PANAMA CITY

RYBAT AQUATIC REDLEG BIOGENESIS ALEXANDER

REF BUENOS AIRES 3615 (IN 37031)

REPORT VOACRS UNABLE ESTABLISH CAUSE REF FAILURE. EVIDENCE ON ALL PREVIOUS UNITS INDICATE FAILURES DUE ABNORMAL LINE CONDITION ALEXANDER.

RECOMMEND BIOGENESIS CHECK LINE SIX TO INSURE IT NOT COMING IN CONTACT WITH AC LINE; ALSO CHECK LINE TO DETERMINE IF ABNORMAL VOLTAGES PRESENT.

FILES 4-137-103/A AND 74-130-231.

END OF MESSAGE